

1/19




FIG. 1

MARKING CYCLE

NM PC NM PMS CM PC CM PMB CM PMC NM

MARKING OPERATION

FIG. 6

2/19




FIG. 2




FIG. 3

3/19




FIG. 4

4/19




FIG. 5

5/19




FIG. 7

6/19




FIG. 8

7/19




FIG. 9

8/19




FIG. 10




FIG. 11



9/19




FIG. 12

10/19




FIG. 13

11/19




FIG. 14




FIG. 15

12/19




FIG. 16

13/19




FIG. 17

14/19




FIG. 18

15/19




FIG. 19




FIG. 22

16/19




FIG. 20



17/19




FIG. 21

18/19




FIG. 23

19/19

